00684.002986.1 <u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Yutaka BAN, et al.

Yutaka BAN, et al.

Appl. No.: 10/700,825

Filed: November 5, 2003

For: TONER SUPPLYING CONTAINER
AND IMAGE FORMING APPARATUS

Examiner: Quana Grainger

Confirmation No.: 2852

Confirmation No.: 6249

Patent No.: 7,292,811 B2

Issue Date: November 6, 2007

April 14, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However,

the Commissioner is authorized to charge any underpayment or credit any overpayment to

Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by

telephone at (202) 530-1010. All correspondence should continue to be directed to our address

given below.

Respectfully submitted,

/William M. Wannisky/

William M. Wannisky Attorney for Patentees Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

Facsimile: (212) 218-2200

WMW/kag

- 2 -

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,292,811 B2

DATED: November 6, 2007

INVENTOR(S): Yutaka Ban, et al. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 44, "above described" should read --above-described--.

COLUMN 7:

Line 33, "above" should read --above---; and

Line 65, "above described" should read -- above-described--.

COLUMN 15:

Line 63, "resiliency o" should read --resiliency of--.

COLUMN 17:

Line 50, "above described" should read --above-described; and

Line 58, "above described" should read -- above-described--.

COLUMN 18:

Line 18, "rides" should read --ride--.

COLUMN 23:

Line 1, "above described" should read --above-described--;

Line 14, "above described" should read --above-described--; and

Line 39, "above described" should read --above-described--.

COLUMN 25:

Line 1, "above described" should read --above-described--;

Line 24, "above described" should read --above-described--.

COLUMN 27:

Line 45, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. 7,292,811 B2

No. of add'l. copies @ 30¢ per page



Staple Here Only! WINT S.ABINIRA

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. 7,292,811 B2

November 6, 2007 **DATED**

Yutaka Ban, et al. Page 2 of 2 INVENTOR(S) :

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 28:

Line 25, "pulled" should read --pull--; and

Line 37, "above described" should read --above-described--.

COLUMN 21:

Line 25, "and" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. 7,292,811 B2

